Inspection Report

By Sri.Muniyappa.G.M
Retd Executive Engineer

Name of Work: Construction of Culverts and damaged covering slab in Dasarahalli in Ward No:15 Darasahalli Sub Division

B.R.No: 304 Date:30-06-2014

Estimate Cost: Rs.5.00 Lakhs

Bill Amount: Rs.494693/-

Date of Inspection: 22-10-18

Observation and Conclusion: The above said Work - Construction of Culverts and damaged Covering Slab in Dasarahalli in Ward - (15) - has been shown by the Concerned AE.

The above said Work has been inspected along with the Concerned AE.

The Measurements are checked by me and it is found Satisfactory.

The Work done is Satisfactory.

G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Name of Work: Construction of Culverts and damaged covering slab in Dasarahalli in Ward No:15 Darasahalli Sub Division

B.R.No: 304 **Date:30-06-2014**



INDEX

Improvement & Covering Slab to Drains.

N.

Total length of Drain R/S. 109.80 Mt

L/S — 109.80 Mt

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

G.M.MUNIYAPPA
B.E.(ELECT),B.E.(CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Construction of Culverts and damaged covering slab in Dasarahalli in Ward No:15 Darasahalli Sub Division

B.R.No: 304 **Date:30-06-2014**

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಧಿಯಂತರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಪಾಲಿಕೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Inspection Report

By Sri.Muniyappa.G.M
Retd Executive Engineer

Name of Work: Construction of Culverts and damaged covering slab in Dasarahalli in Ward No:15 Darasahalli Sub Division

B.R.No: 304 **Date:30-06-2014**

Estimate Cost: Rs.5.00 Lakhs

Bill Amount: Rs.494693/-

Date of Inspection: 22-10-18

Observation and Conclusion: The above said Work - Construction of Culverts and damaged Covering Slabs in Dasarahalli in Ward - (15) - has been shown by the Concerned AE.

The above said Work has been inspected along with the Concerned AE.

The Measurements are checked by me and It is found Satisfactory.

The Work done is Satisfactory.

G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಕುಂಟೆ, ಬೆಂಗಳೂರು

Name of Work: Construction of Culverts and damaged covering slab in Dasarahalli in Ward No:15 Darasahalli Sub Division

B.R.No: 304 **Date:30-06-2014**



Total length of Drain R/S. 109.80 Mt

L/S — 109.80 Mt

G.M.MUNIYAPPA
B.E.(ELECT),B.E, (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು
ಬೆಂಗಳೂರು